

Inspection Photos

4/19/2019

Operator: D90 ENERGY LLC - 10706

Location ID: 435480

Inspection Doc. Number: 682504787

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Doc. Number: 682504787



Photo 2: Photo taken from the southeast end of the location, facing north. Photo shows interim and production areas.



Photo 3: Photo taken from the southeast end of the location, facing northwest. Photo shows interim and production areas.

Inspection Photos
Operator: D90 ENERGY LLC - 10706
Location ID: 435480



Photo 4: Photo taken from the southeast end of the location, facing west. Photo shows interim and production areas.



Photo 5 Photo taken from the south end of the location. Photo shows insufficient stormwater BMPs to allow for sediment laden free stormwater discharge from the location. Photo shows erosion degradation and stormwater runoff transporting sediment beyond location onto adjacent lands.



Photo 6: Photo taken from the south end of the location. Photo shows insufficient stormwater BMPs at the ditch to allow for sediment laden free stormwater discharge from the location.

Inspection Photos
Operator: D90 ENERGY LLC - 10706
Location ID: 435480



Photo 7: Photo shows stormwater erosion degradation on location/interim areas.



Photo 8: Photo taken from the southeast end of the location, facing west. Photo shows insufficient stormwater BMPs at the ditch to allow for sediment laden free stormwater discharge from the location. Photo also shows sediment deposition on the interim area.



Photo 9: Photo taken from the southeast end of the location, facing east. Photo shows insufficient stormwater BMPs to allow for sediment laden free stormwater discharge from the location. Photo also shows erosion degradation, and sediment deposition on the interim area and areas off location.



Photo 10: See comments under photo 9.



Photo 11: Photo taken from the southwest end of the location, facing north. Photo shows interim and production areas. Photo also shows perimeter stormwater ditch.



Photo 12: Photo taken from the southwest end of the location, facing east. Photo shows interim and production areas. Photo also shows perimeter stormwater ditch.



Photo 13: Photo taken from the northwest end of the location, facing south. Photo shows interim and production areas. Photo also shows perimeter stormwater ditch.



Photo 14: Photo taken from the northwest end of the location, facing east. Photo shows interim and production areas. Photo also shows perimeter stormwater ditch.



Photo 15: Photo shows secondary containment BMPs in proper functioning condition.



Photo 16: Photo shows barrels have been properly stored within secondary containment.



Photo 17: Photo shows porta-john has been properly secured.



Photo 18: Photo taken from the location, facing west. Photo shows the ten (10) tanks at the battery. Tanks appears have tank contents and NFPA labelling, however, tanks appear to be missing capacity labeling in accordance with 210.d



Photo 19: See comments under photo 18.



Photo 20: Photo taken from the location, facing north. Photo shows erosion degradation on access road.