

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/16/2019

Submitted Date:

04/16/2019

Document Number:

687904585

**FIELD INSPECTION FORM**

Loc ID 325723 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215294	WELL	PR	02/20/1990	GW	067-06899	HUBERT MORRISON A 1	PR

**General Comment:**

[This is an onsite inspection of this location as required. Photos are at the end of this inspection report.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at location entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on sign at entrance.		Date: _____
Corrective Action:			
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead with PVC bradenhead access.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Pump jack has localized areas around gas powered engine of oily waste and stained gravel that needs to be cleaned up and removed.		
Corrective Action:	Clean up areas of stained gravel in accordance with Rule 907.e. and make sure all fittings are properly secure in accordance with Rule 605.d.		Date: 05/16/2019
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:			Date:
Type: Flow Line	# 6		

Comment:	1-4" steel flowline from wellhead to separator. 1-3" steel flowline from separator to meter house. 1-2" steel flowline from meter house to offsite dogleg. 1-2" steel flowline from separator dump valve to offsite produced water gathering system. 1-1" steel flowline from separator to pumpjack engine fuel gas.  * 1-1" steel flowline from separator to domestic gas tap.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215294 Type: WELL API Number: 067-06899 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Rip Rap	Pass					
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil day tank.

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT
**Attached Documents**
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402011126	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797742">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797742</a>
687904586	Gravel staining around fuel gas scrubber	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797733">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797733</a>
687904587	Gravel staining	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797734">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797734</a>
687904588	Engine leaks.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797735">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797735</a>
687904589	Location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797736">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797736</a>