

Inspection Photos

API: 05-071-06145

Operator: MERIDIAN OIL INC

Inspection Date: 4/2/2019

Inspection Photos



Photo 1. Facing west along the reclaimed access road.

Inspection Photos



Photo 2. Facing west along the reclaimed access road. Vegetation appears to be fully established.

Inspection Photos



Photo 3. Facing west toward the location.. Vegetation appears to be fully established.