

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2019

Submitted Date:

04/23/2019

Document Number:

675002206

**FIELD INSPECTION FORM**

Loc ID 312707 Inspector Name: Wentzel, Dougo On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

- 11 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275664	WELL	PR	09/13/2012	GW	077-08850	CURRIER 1-13 (BK1)	TA

**General Comment:**

[This is a follow up inspection from doc#675001448 Dated 12/7/18](#)  
[Not all corrective actions have been made.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Battery sign has past operator information remaining on sign		
Corrective Action:	Install sign to comply with Rule 210.b		Date: <u>06/24/2019</u>
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<u>911 / Posted Emergency Contact Number 1-800-891-6191</u>		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	unused stored tanks remain on location		
Corrective Action:	Comply with Rule 603.f .		Date: <u>03/11/2019</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>		corrective date
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	#	
Comment: <a href="#">Light plant.</a>		
Corrective Action:		Date:
Type: Other	# 1	
Comment: <a href="#">Pump</a>		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	<a href="#">Install or repair containment liner.</a>			
Corrective Action:	<a href="#">Repair or install berms or other secondary containment devices (liner) per Rule 906.d.(1).</a>			Date: <u>05/23/2019</u>

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 275664 Type: WELL API Number: 077-08850 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well head removed and sitting by seperator.  
A form 4 doc # 401903377 was submitted 1/14/19, Test for SWD conversion

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Ditches	Fail			
Gravel	Pass					
Compaction	Pass					
		Waddles	Pass			
Drains	Fail					
		Compaction				
Berms	Pass					
		Drains	Fail			

Comment: Erosion is evident along unstabilized slope on location .  
Stormwater erosion not being controlled on the location at this time.  
BMP's need repaired or are not being maintained at this time.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/23/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675002207	Inspection 675002206 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4803112">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4803112</a>