

Penrose #1R

Corrective Actions Taken on the Penrose #1R for the COGCC compliance
INC.

Penrose #1R

04/22/19



Storm Water management controls have been established to stabilize erosion. Re-contoured and established drainage on eastern side of project area to stabilize erosion channels on eastern fill slope and to control water run on to adjacent location.



View from adjacent well pad looking north at project area.



View of project area looking north, northwest.

Storm Water management controls have been established to stabilize erosion.
Re-contoured and established drainage on north western side of project area.



View looking west from eastern corner of project area.

Storm Water management controls have been established to stabilize erosion.
Re-contoured and established drainage on eastern fill slope of project area.



View looking north of eastern project area.



View looking northwest of eastern project area.

Re-contoured and established drainage on north eastern fill slope of project area, marked guy line anchor eastern project area with T-Post.



View looking east of northeastern project area.



View of guy line anchor eastern project area.