

Interim Reclamation and Stormwater Inspection

April 23, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 331615

Inspection Document #: 674902801

Weld County, CO

SWSE Section 27 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /1N67W27

Location ID: 331615



Photo 1. Photo taken from the access road, facing Northeast. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations at the location.



Photo 2. Photo taken from access road, facing North. Operator does not appear to have implemented and maintained Best Management Practices (BMPs) to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation per Rule 1002.f.(2). Operator does not appear to have implemented BMPs in accordance with good engineering practices per Rule 1002.f.(2).

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /1N67W27

Location ID: 331615



Photo 3. Photo taken from the access road, facing North. See comments from Photo 2.



Photo 4. Photo taken from the access road, facing South. See comments from Photo 2.

Inspection Photos
Location Name: KERR MCGEE OIL & GAS /1N67W27
Location ID: 331615



Photo 5. Photo taken from the location, facing Northwest. See comments from Photo 2.



Photo 6. Photo taken from the southern perimeter of the location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /1N67W27

Location ID: 331615



Photo 7. Photo taken from the northeastern perimeter of the location, facing Southwest. See comments from Photo 1.



Photo 8. Photo taken from the southern perimeter of the location, facing South. See comments from Photo 1.