

Inspection Photos
Location Name: McCallum Unit 192
API: 05-057-06446



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Non reportable spill. Stained soil at wellhead.