

# Interim Reclamation and Stormwater Inspection

April 23, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 429182

Inspection Document #: 674902803

Weld County, CO

SWSE Section 6 T2N R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS /2N65W6

Location ID: 429182



**Photo 1.** Photo taken from the access road, facing Northwest. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations at the location.



**Photo 2.** Photo taken from access road looking into the location, facing Northwest. Operator does not appear to have implemented and maintained Best Management Practices (BMPs) to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation per Rule 1002.f.(2). Operator does not appear to have implemented BMPs in accordance with good engineering practices per Rule 1002.f.(2).

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /2N65W6

Location ID: 429182



**Photo 3.** Photo taken from the location, facing North. See comments from Photo 1.



**Photo 4.** Photo taken from access road looking into the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /2N65W6

Location ID: 429182



**Photo 5.** Photo taken from the location. See comments from Photo 1.



**Photo 6.** Photo taken from the location, facing Southeast. See comments from Photo 2.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /2N65W6

Location ID: 429182



**Photo 7.** Photo taken from the location, facing South. See comments from Photo 2.



**Photo 8.** Photo taken from the southern perimeter of the location, facing West. See comments from Photos 1 and 2.