

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/23/2019

Submitted Date:

04/24/2019

Document Number:

682504811**FIELD INSPECTION FORM**
 Loc ID 312196 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10380Name of Operator: BENCHMARK ENERGY LLCAddress: PO BOX 8747City: PRATT State: KS Zip: 67124**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219394	WELL	TA	12/01/2010	ERIW	075-06281	MOUNT HOPE UNIT W-36	RI

**General Comment:**

On April 23rd, 2019, Reclamation Specialist Trujillo and ODO Reclamation Specialist Conklin met with contractors to go over a bid packet for stormwater, weed and vegetation maintenance on Benchmark locations in the Mount Hope field. This inspection is to document the current conditions of the location, and to identify potential degradation and noxious weed issues.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment: No issues observed.

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Erosion degradation evident on access road to the east of the location. Additionally, head-cuts evident on areas of the north, and northeast end of the location.

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682504812	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805121</a>