

Inspection Photos
Location Name: Ivey#16-11
Location ID: 320506



Photo 1 WH



Photo 2 TNK BTYR Located in flood plain inadequate berms

Inspection Photos
Location Name: Ivey#16-11
Location ID: 320506



Photo 3 Sep/meter house and ECD. Located in a flood plain inadequate berms.



Photo 4 Tank located in view of county roads paint in disrepair.

Inspection Photos
Location Name: Ivey#16-11
Location ID: 320506



Photo 5 Tank located in view of county roads paint in disrepair.



Photo 6 Paint chips from crude oil tank around berm of tank.