

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2019

Submitted Date:

04/18/2019

Document Number:

675002190**FIELD INSPECTION FORM**
 Loc ID 312507 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221808	WELL	SI	06/12/1983	GW	077-08410	FEDERAL 25-3	TA

General Comment:

This is a follow up inspection to FIR Doc#689401238 dated 5/17/18, and inspection Doc#675001852 dated 1/29/19

This well is included in the AOC # 1V-609.

No corrective actions have been made at this time.

Location				
Lease Road:				
Type	Access			
comment:	No maintenance has been made to access road			
Corrective Action:	Repair and maintain lease road to comply with rule 204.			Date: 03/03/2019
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-858-8550			
Corrective Action:				Date:
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Risers on location, Risers not marked or locked out Taged out			
Corrective Action:	Comply with Rule 603.f .			Date: 03/04/2019
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Other	#			corrective date
Comment:	No equipment on location Only a fenced well head and 4 risers are on this location			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:



Inspected FacilitiesFacility ID: 221808 Type: WELL API Number: 077-08410 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: No current Form 4 on file for continued TA status. According to AOC 1V-609 order #11 annual submission is still required
. I find no evidence of this form filed, last form 4 file 12/29/16

Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.

Date: 06/18/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Fail			
Compaction	Pass					
		Compaction	Fail			
Sediment Traps	Fail					
Drains	Fail					
Ditches	Pass					

Comment: Stormwater erosion not being controlled on the location at this time.
BMP's need repaired or are not being maintained at this time.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/18/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402013499	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4799763
675002191	Inspection 675002190 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4799761