

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2019

Submitted Date:

04/18/2019

Document Number:

678302440

**FIELD INSPECTION FORM**

|   |                                     |   |                   |   |
|---|-------------------------------------|---|-------------------|---|
| Loc ID<br>431932  | Inspector Name:<br>GINTAUTAS, PETER | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| <b>Operator Information:</b><br>OGCC Operator Number: 47120<br>Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP<br>Address: P O BOX 173779<br>City: DENVER State: CO Zip: 80217- |                                     |   |                   | <b>Findings:</b><br>3 Number of Comments<br>1 Number of Corrective Actions<br><input checked="" type="checkbox"/> Corrective Action Response Requested  |
|   |                                     |   |                   | <b>ANY CORRECTIVE ACTION(S) FROM<br/>PREVIOUS INSPECTIONS THAT HAVE NOT<br/>BEEN ADDRESSED ARE STILL APPLICABLE</b>   |

**Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
| , Anadarko   |       | COGCCinspections@Anadarko.com |         |

**Inspected Facilities:**

| Facility ID | Type                | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|---------------------|--------|-------------|------------|-----------|---------------------|-------------|
| 431929      | WELL                | PR     | 11/01/2018  | OW         | 123-36870 | THOMSEN 36C-18HZ    | EI          |
| 431930      | WELL                | PR     | 11/01/2018  | OW         | 123-36871 | THOMSEN 13C-18HZ    | EI          |
| 431931      | WELL                | PR     | 11/01/2018  | OW         | 123-36872 | THOMSEN 36N-18HZ    | EI          |
| 431933      | WELL                | PR     | 11/01/2018  | OW         | 123-36873 | THOMSEN 14N-18HZ    | EI          |
| 439755      | WELL                | PR     | 12/01/2018  | OW         | 123-40547 | THOMSEN 2N-31HZ     | EI          |
| 439757      | WELL                | PR     | 11/01/2018  | OW         | 123-40548 | THOMSEN 5N-31HZ     | EI          |
| 439775      | WELL                | PR     | 11/01/2018  | OW         | 123-40555 | THOMSEN 4N-31HZ     | EI          |
| 440334      | SPILL OR<br>RELEASE | CL     | 11/28/2014  |            | -         | SPILL/RELEASE POINT | EI          |

**General Comment:**

production facilities not co-located with wells and battery not inspected in this report.

**Location**Overall Good: ☒**Signs/Marker:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | CONTAINERS  |       |  |
| Comment:           | WCW 4610C combined product (mostly CH3OH with other compounds)<br>Unused CH3OH drums also labeled as to former contents, Drums appear empty |       |  |
| Corrective Action: |   | Date: |  |
| Type               | WELLHEAD  |       |  |
| Comment:           |   |       |  |
| Corrective Action: |   | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  | Date: _____ |
| Corrective Action: |  |             |

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | UNUSED EQUIPMENT  |       |            |
| Comment:           | see attached photos of empty methanol drums inside fencing. 2 drums at 36N-18HZ and 1 drum at 13C-16HZ<br>see photos attached |       |            |
| Corrective Action: | Comply with Rule 603.f .  | Date: | 05/18/2019 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: spill 440334 reported in 2014 at wellhead of 2N-31HZ No indications at surface of impacts from water based mud spill in 2014. spill closed in 2014 based on data submitted by form 19 process.

☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 7 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL           | 1 |          | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   | Date:    |           |         |        |

**Paint**

|           |  |
|-----------|--|
| Condition |  |
|-----------|--|

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities       |                       |                              |                   |                         |
|----------------------------|-----------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>431929</u> | Type: <u>WELL</u>     | API Number: <u>123-36870</u> | Status: <u>PR</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>431930</u> | Type: <u>WELL</u>     | API Number: <u>123-36871</u> | Status: <u>PR</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>431931</u> | Type: <u>WELL</u>     | API Number: <u>123-36872</u> | Status: <u>PR</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>431933</u> | Type: <u>WELL</u>     | API Number: <u>123-36873</u> | Status: <u>PR</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>439755</u> | Type: <u>WELL</u>     | API Number: <u>123-40547</u> | Status: <u>PR</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>439757</u> | Type: <u>WELL</u>     | API Number: <u>123-40548</u> | Status: <u>PR</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>439775</u> | Type: <u>WELL</u>     | API Number: <u>123-40555</u> | Status: <u>PR</u> | Insp. Status: <u>EI</u> |
| Facility ID: <u>440334</u> | Type: <u>SPILL OR</u> | API Number: <u>-</u>         | Status: <u>CL</u> | Insp. Status: <u>EI</u> |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402014418    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800280">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800280</a> |
| 678302441    | unused drums         | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800272">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800272</a> |
| 678302442    | unused drum          | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800273">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800273</a> |