

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2019

Submitted Date:

04/18/2019

Document Number:

679703772

**FIELD INSPECTION FORM**

Loc ID 316020 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
9 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10539  
 Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
 Address: 1125 ESCALANTE DR  
 City: RANGELY State: CO Zip: 81648

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231931	WELL	PR	09/07/1993	GW	103-09602	DRAGON TRAIL UNIT 1150	PR
266563	WELL	PA	09/04/2007	GW	103-10280	DTU 1160	PA

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 4/17/2019 at approximately 12:00, I, inspector Rick Moran, conducted a follow up inspection at Utah Oil & Gas well Dragon Trail Unit 1050 in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679702827 along with a routine well inspection.

During this inspection the following possible compliance issues were observed.

- 1) The tank secondary containment liner is torn.
- 2) Trash that ran off from location through a breached berm.
- 3) Storm water run off from location through a breached berm.
- 4) Soil scour on southeast hillside of location.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679703772.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	TRASH		
Comment:	Plastic pipe end caps 5' to 30' northwest of location in breached berm channels.		
Corrective Action:	Comply with Rule 603.f .	Date:	04/30/2019

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		39.861690,-108.856580
Comment:	Pond located 340' northwest of tank.				

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				Inadequate
Comment: <b>Inadequate berms around tanks(s).</b> <b>Liner is degraded.</b>				
Corrective Action: <b>Repair or install berms or other secondary containment devices per Rule 906.d.(1).</b>				Date: <u>03/08/2019</u>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 231931 Type: WELL API Number: 103-09602 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well on plunger lift.

Corrective Action:

Date:

Facility ID: 266563 Type: WELL API Number: 103-10280 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: P&A marker on location.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: [Location soil run off identified on the southwest to northwest side through breaches in the berm along the edge of the location.](#)  
[Soil scour on the southeast hillside of the location.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 05/20/2019

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402014421	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800282">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800282</a>
679703773	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800275">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800275</a>