

# Interim Reclamation and Stormwater Inspection

April 24, 2019

Operator: CCRP OPERATING INC- 10665

Location ID: 456179

Inspection Document #: 697500020

Weld County, CO

NENE Section 23 T12N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

# Inspection Photos

Location Name: True Ranch Fee /2326 East

Location ID: 456179



**Photo 1.** Photo taken from the southeastern location, facing North. Operator has installed permanent stormwater BMPs (ditch and sediment); however, the permanent stormwater BMPs are not in proper functioning condition. Soil particle deposition as a result of wind erosion has filled in ditches and the sediment trap, and soil particle deposition was observed off Location. Operator has failed to adequately stabilize the well pad to control dust and wind erosion.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 2.** Photo taken from the southeastern perimeter of the location, facing South. Photo illustrates the sediment trap which has been filled in with soil particle deposition as a result of wind erosion from the well pad not being adequately stabilized. Also, it doesn't appear that the sediment trap has been adequately sized for the disturbance area.

Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 3.** Photo taken from the southern location, facing East. Photo illustrates stormwater erosion which further indicates the well pad has not been adequately stabilized.



Inspection Photos

Location Name: True Ranch Fee /2326 East

Location ID: 456179



**Photo 4.** Photo taken from the southern location, facing West. See comments under Photo 3.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 5.** Photo taken from the southwestern location, facing Southwest. See comments under Photo 3.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 6.** Photo taken from the southwestern location, facing North. This area was used for the MLVT storage during drilling operations. The area has been seeded and straw crimped with mulch. Germination was observed throughout the western area where the Operator has performed Interim Reclamation for the MLVT storage area.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 7.** Photo taken from the southwestern location, facing North. Operator has the Production Facility equipment located along the northwestern well pad area. Cut slopes has been tracked with equipment, seeded and hydromulched. Wattles have been installed along the top of the northern cut slope.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 8.** Photo taken from the western cut slope, facing North. See comments under Photo 7.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 9.** Photo taken from the northwestern cut slope, facing East. See comments under Photo 7. Also, topsoil has been stored along the northern location. Topsoil stockpiles have been seeded and straw crimped with mulch. Germination was observed throughout the topsoil stockpiles.