

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2019

Submitted Date:

04/25/2019

Document Number:

685100828**FIELD INSPECTION FORM**Loc ID 320360 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gillette, Kira		kira.gillette@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Brown, Devin		dbrown@petrosharecorp.com	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203546	WELL	PR	11/01/2018	OW	001-09106	AMBUSH 24-22	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Stained soil around PU motor and base, and wellhead. see pic 3 & 4

Corrective Action:

Properly treat or dispose of oily waste in accordance with 907.e Delinquent. 2/8/19

Date: 02/08/2019

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

PUMP JACK

Comment:

fabricated fence around pump jack.

Corrective Action:

Date:

Equipment:

corrective date

Type: Other

1

Comment:

Bradenhead appears to be plumbed to surface.

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Automation Equipment.

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Unused pump jack, horses head, and other equipment on location. See pic 1&2

Corrective Action:

Comply with Rule 603.f .

Date: 07/25/2019

Type: Prime Mover

1

Comment:

Gas powered motor.

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID: 203546	Type: WELL	API Number: 001-09106	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Well appears to be producing.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 4/25/2019 at approximately 1030 I, Inspector Justin Medina conducted an on-site inspection at Ambush 24-22 Petroshare Corp. at 001-09106 in Adams County Colorado. While there, I observed producing well.</p> <p>This is a follow up inspection from Document # 688401011</p> <p>At time of inspection the following possible compliance issues were found:</p> <p>Unused pump jack, horses head, and other equipment on location. See pic 1&2</p> <p>Comply with Rule 603.f . 7/25/19</p> <p>Stained soil around PU motor and base. See pic 3&4</p> <p>Properly treat or dispose of oily waste in accordance with 907.e Delinquent. 2/8/19</p> <p>Other CA from previous inspection appear to have been addressed.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	medinaj	04/25/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100829	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806887