

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2019

Submitted Date:

04/25/2019

Document Number:

679703873**FIELD INSPECTION FORM**

Loc ID 315344	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 7 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>51130</u> Name of Operator: <u>LOCIN OIL CORPORATION</u> Address: <u>2445 TECHNOLOGY FOREST BD #710</u> City: <u>THE WOODLANDS</u> State: <u>TX</u> Zip: <u>77381</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Nicol, Michael	281-362-8600x116	mnicol@locinoil.com	All inspections
Thompson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230668	WELL	PR	10/22/2000	GW	103-08336	FORK UNIT-FEDERAL 7-12-1-2	PR

**General Comment:**

COGCC Inspection Report Summary.

On 4/25/2019 at approximately 17:30, inspector Rick Moran, conducted a follow up inspection at in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679702104 and FIRR document 401991957.

During this inspection all the corrective actions identified were resolved:

- 1) pit permit.

During this inspection additional possible compliance issues were observed:

- 1) Gas leaking from the separator.
- 2) Storm water entering the pit and over flowing the berm.
- 3) Pit < 2' of free board.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679703873.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-574-7607 or 7609

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	Gas leaking at connection on side of separator.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/24/2019
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 230668	Type: WELL	API Number: 103-08336	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	Producing well on plunger lift.		
Corrective Action:		Date:	

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Storm water erosion from the lease road entrance running onto the location and into the pit. The opposite exterior side of the pit is wet indicating the storm water has filled the pit then over flowed the pit berm.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/24/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: Pit ID: Lat: 39.973730 Long: -108.792070

Reference Point: Other: Length: Width:

**Lining:**

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: NO

Comment: Pit needs > 2' of freeboard. Storm water soils are running into the pit.

Corrective Action

Install or repair required BMPs per Rule 1002.f.

Date: 05/24/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679703874	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4807132">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4807132</a>