

Inspection Photos
Operator: BP America
Location/API #: 067-08831
Date: 4-17-2019



Photo 1. View of the western project area from the northern edge facing southward.



Photo 2. View of erosional channel within the western project area. Cobble placed within channel is not an effective stormwater control and erosion is continuing.



Photo 3. View of wattle at the bottom of the slope that is full of sediment.



Photo 4. View of cobble within erosional channel and straw wattle that does not appear to be functioning properly.