

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/29/2019

Submitted Date:

04/29/2019

Document Number:

694400146

FIELD INSPECTION FORM
 Loc ID 450197 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Extraction		COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450197	LOCATION	AC			-	McGirr 26-L	AC

General Comment:

Inspected Facilities			
Facility ID:	450197	Type:	LOCATION
API Number:	-	Status:	AC
Insp. Status:	AC		
Producing Well			
Comment:	AC		
Corrective Action:		Date:	
Complaint			
Comment:	<p>Inspection in response to complaint. 18#200447182</p> <p>Field Inspector Assigned: Adam Kraich</p> <p>Complaint Received:</p> <p>Date: 4-26-2019</p> <p>Complaint Contacted:</p> <p>Date: 4-29-2019 @11:01</p> <p>Location #: 450197</p> <p>Inspection Document #: 694400146</p> <p>Nature of complaint: Noise</p> <p>Field Inspector Actions:</p> <p>On 4-26-2019 I Adam Kraich, received a complaint in regard to noise suspected to coming from the McGirr 26-Ln location, owned and operated by Extraction Oil & Gas. On 4-26-2019, I visited the location and measured sustained wind speeds in excess of 5mph. I did not perform a sound audit at that time due to weather conditions. While at the location, I informed XOG regulatory management via phone call, of the nature of the complaint.</p> <p>On 4-29-2019, I performed a sound audit in response to the complaint as guided by rule 802. Wind speeds were observed with maximum gusts at 3.79mph out of the west/northwest and no measurable (zero) sustained speed. The sound audit performed at 40.36874, -104.96778. With a start time of approximately 10:17am, and completed at approximately 10:48am. The LEQ average was determined to be at 68.8DB over the course of the study. This indicates non-compliance under COGCC rule 802.</p> <p>See inspection document for corrective action detail.</p> <p>All information reviewed and site inspection information were submitted to the complaint specialist for further review.</p>		
Corrective Action:	Comply with Rule 802. Identify and install control measures.		Date: 05/02/2019

COGCC Comments		
Comment	User	Date
Inspection in response to complaint.	kraicha	04/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400147	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4809532
694400148	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4809533