

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	No signage of contents of tank on location. See pics 7 & 8		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 06/23/2019
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Other	Tank	>= 5 bbls	
Comment:	What appears to be stained soil behind produced water tanks. Approx 20' X 10'. Stormwater taking stained soil into ditch around location. See pic 24, 25,26,27,28,29,30,31		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 05/23/2019
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	6' Chain Link Fence around Tanks, and all other production equipment.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	6' Chain link fence around all seperators and other production equipment.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Ancillary equipment	# 14		
Comment:	Automation equipment.		
Corrective Action:			Date:
Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Dehydrator	# 4		
Comment:			
Corrective Action:			Date:
Type: Gathering Line	# 11		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment:	Wells on location appear to be plumbed to surface.		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 2		
Comment:			
Corrective Action:			Date:
Type: LACT	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLS	STEEL AST		40.050190,-104.695990
Comment:	Unused, uncapped, and no placard on tank that shows contents. See pic 7&8				
Corrective Action:	Comply with Rule 603.f .				Date: 07/23/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	PBV STEEL		40.059050,-104.696410
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	PBV STEEL		40.059050,-104.696410
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		Shares containment with oil tank.			
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	9	500 BBLs	LVST		40.059250,-104.695350
Comment:		Mobile tanks inside containment.			
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 454373 Type: WELL API Number: 123-46521 Status: DG Insp. Status: PR

Facility ID: 454375 Type: WELL API Number: 123-46522 Status: DG Insp. Status: PR

Facility ID: 454376 Type: WELL API Number: 123-46523 Status: DG Insp. Status: PR

Facility ID: 454377 Type: WELL API Number: 123-46524 Status: DG Insp. Status: PR

Facility ID: 454378 Type: WELL API Number: 123-46525 Status: DG Insp. Status: PR

Facility ID: 454379 Type: WELL API Number: 123-46526 Status: DG Insp. Status: PR

Facility ID: 454380 Type: WELL API Number: 123-46527 Status: DG Insp. Status: PR

Producing Well

Comment: [Wells on location appear to be producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 4/23/2019 at approximately 1130 I, Inspector Justin Medina conducted an on-site inspection at English Farm 8-6HZ Anadarko at 123-46525 in Weld County Colorado. While there, I observed producing well. During this inspection the following possible compliance issues were observed: No signage of contents of tank on location. See pics 7 & 8 Install sign to comply with Rule 210.d. 6/23/19 What appears to be stained soil behind produced water tanks. Approx 20' X 10'. Stormwater taking stained soil into ditch around location. See pic 24, 25,26,27,28,29,30,31 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 5/23/19 At time of inspection I talked to Anadarko Employee Victor and informed him of stained soil behind water tanks. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	04/23/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402018915	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4804214
685100811	Loc Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4804210