

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2019

Submitted Date:

04/24/2019

Document Number:

679703844

**FIELD INSPECTION FORM**

Loc ID 398807 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 6720  
Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
Address: 621 17TH ST STE 2300  
City: DENVER State: CO Zip: 80293

**Findings:**

- 12 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	<a href="#">All inspections</a>
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277804	WELL	PR	04/15/2009	GW	103-10580	WEAVER RIDGE 13-9	PR
418872	WELL	PR	08/09/2012	OW	103-11781	Weaver Ridge 13-9 H	PR
418876	WELL	PR	01/27/2011	GW	103-11782	Weaver Ridge 13-16	PR

**General Comment:**

COGCC Inspection Report Summary.

On 4/24/2019 at approximately 7:45, inspector Rick Moran, conducted a follow up inspection at Robert L Bayless well Weaver Ridge 13-9 in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679702652. The well inspection was limited due to a rig on location. Equipment located within the guide wires of the rig was not inspected.

During this inspection the following corrective action was identified as resolved:

- 1) The tank capacity labels.

Corrective actions not completed:

- 1) Removal of partially melted lead batteries.

Undetermine if corrective actions were completed due to the rig on location:

- 1) Two containers without labels.
- 2) Missing well head sign for well 13-9.

During this inspection the following possible compliance issues were observed:

- 1) Gas leaking at the separator.
- 2) Open buckets of fluid next to separator.
- 3) Oily stained soil near pump jack motor.
- 4) Open container of fluid over flowing with oily stained soild next to separator.
- 5) Unmarked deadman.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679703844.

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-327-0880		Date:
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Partially melted lead batteries on location.		
Corrective Action:	Comply with Rule 603.f.		Date: 02/15/2019
Type	OTHER		
Comment:	Open buckets with unknown fluid stored in secondary containment next to separator.		
Corrective Action:	Comply with Rule 603.f .		Date: 05/08/2019
Type	OTHER		
Comment:	Oily stained soil next to pump jack.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 05/24/2019
Type	OTHER		
Comment:	Oily stained soil next to separator with open container of fluid over flowing unto the ground.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 05/24/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Horizontal Heated Separator	#		corrective date
Comment:	Separator leaking gas.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 05/24/2019
Type: Deadman # & Marked	#		
Comment:	One guy line anchor not marked at lease road entrance.		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 05/10/2019
<b>Venting:</b>			

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: <u>277804</u>	Type: <u>WELL</u>	API Number: <u>103-10580</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:	<u>All wells idle at time of inspection. Rig on one well.</u>		
Corrective Action:		Date:	
Facility ID: <u>418872</u>	Type: <u>WELL</u>	API Number: <u>103-11781</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:	<u>All wells idle at time of inspection. Rig on one well.</u>		
Corrective Action:		Date:	
Facility ID: <u>418876</u>	Type: <u>WELL</u>	API Number: <u>103-11782</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:	<u>All wells idle at time of inspection. Rig on one well.</u>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402020538	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805470">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805470</a>
679703845	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805464">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805464</a>