

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2019

Submitted Date:

04/24/2019

Document Number:

687904651**FIELD INSPECTION FORM**
 Loc ID 333598 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 8455Name of Operator: BIG RUN PRODUCTION COMPANYAddress: 318 WEST RUSKCity: TYLER State: TX Zip: 75701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Pickard, Joan	(800) 256-2990	elirebichoil@suddenlinkmail.com	All Inspections
Guffey, Ken	970-883-2314	croudine@centurytel.net	Pumper

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214729	WELL	PR	12/01/2015	GW	067-06333	ARGENTA FEE 17	PR

General Comment:[Site inspection with photos at the end of this inspection report.](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank labels and placards missing contact information, type of fluid and tank capacity.		
Corrective Action:	Comply with Rule 210.d.	Date:	05/24/2019
Type	WELLHEAD		
Comment:	Wellhead sign posted. Also posted on meter house door but in very poor condition and needs to be updated with current contact information.		
Corrective Action:	Comply with Rule 210.e.	Date:	05/24/2019

Emergency Contact Number:

Comment:	Emergency contact information not updated. Current number (970) 883-2314 called multiple times. seems to be disconnected.		
Corrective Action:	Comply with Rule 210.b.	Date:	05/24/2019

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused piping laying in secondary containment of tank and along separator should be removed.		
Corrective Action:	Comply with Rule 603.f.	Date:	05/24/2019
Type	UNUSED EQUIPMENT		
Comment:	5 unused Barton chart recorders are sitting in meter house and not in use. Remove unused equipment.		
Corrective Action:	Comply with Rule 603.f.	Date:	05/24/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bird Protectors	# 1		corrective date
Comment:	On separator stack.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with no bradenhead access.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Flow Line	# 3	
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to offsite dogleg.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PBV STEEL		,
Comment:	Tank missing labels and placards and information. See CA stated under signs/markers tab.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 214729	Type: WELL	API Number: 067-06333	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Porducing.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402020409	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805382
687904652	Location sign w/incorrect contact.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805377
687904653	Incorrect tank labels and unused piping.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805378
687904654	unused piping by separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805379
687904655	Unused equipment chart recorders.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805380
687904656	Meter house door sign illegible	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805381