



**Inspected Facilities**

Facility ID: 463844 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: COGCC investigation of spill reported by Operator after discovery of discrepancy in produced water volumes/tank level. Operator has begun initial pothole investigation near buried produced water tank. Operator to submit results of investigation and root cause/corrective action via Form 19 Supplemental Report within 90 days. Submit Form 27 Site Investigation and Remediation Workplan if more detailed investigation is required or onsite treatment of oily impacted material is proposed.

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700171	WahlertTankBatteryPhotos 4-30-2019	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811487">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811487</a>