

GOLDEN EAGLE 19-06 API# 05-071-08698 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 22, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401795



PHOTO 1: THE STAINED SOIL AROUND THE WELL HEAD HAS BEEN REMOVED FROM LOCATION.

GOLDEN EAGLE 19-06 API# 05-071-08698 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 22, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401795



PHOTO 2: THE UNUSED SOUND WALLS HAVE BEEN REMOVED FROM LOCATION.

GOLDEN EAGLE 19-06 API# 05-071-08698 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 22, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401795



PHOTO 3: A DIRT BERM WAS ESTABLISHED AROUND THE PRODUCTION PIT.

GOLDEN EAGLE 19-06 API# 05-071-08698 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 22, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401795



PHOTO 4: A DIRT BERM WAS ESTABLISHED AROUND THE PRODUCTION PIT.

GOLDEN EAGLE 19-06 API# 05-071-08698 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 22, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401795



PHOTO 5: THE EROSION RILL ON THE FILL SLOPE WAS FILLED IN.

GOLDEN EAGLE 19-06 API# 05-071-08698 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 22, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401795




PHOTO 6: THE DIRT BERM WAS DOMINATED ON THE EAST SIDE OF THE WELL PAD TO DIRECT STORMWATER RUN OFF TO THE EXISTING ARMOR ON THE SOUTHEAST CORNER OF THE WELL PAD.