

# Inspection Photos

API: 05-071-06338

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 5/1/2019

## Inspection Photos



**Photo 1.** Facing west along the main access road. There is vehicle rutting along the road causing road damage.



## Inspection Photos



**Photo 2.** There are deep vehicle ruts along the road. Stormwater is accumulating on the road.



## Inspection Photos



**Photo 3.** No issues were observed at the location.