

Inspection Photos
Location Name: Mc Williams 2-31
API: 05-081-06351



Photo 1. Overview of location taken at entrance facing south.



Photo 2. Erosion rills and sediment leaving location.

Inspection Photos
Location Name: Mc Williams 2-31
API: 05-081-06351



Photo 3. Sediment leaving location.



Photo 4. Erosion rills and sediment leaving location.

Inspection Photos
Location Name: Mc Williams 2-31
API: 05-081-06351



Photo 5. Rill leaving pit.



Photo 6. Rill from pit leaving location.