

**Inspection Photos**  
**Location Name: Carpenter 2-32**  
**API: 05-081-05363**



**Photo 1. Overview of location taken at entrance facing southeast.**



**Photo 2. Non reportable spill – stained soil.**



Inspection Photos  
Location Name: Carpenter 2-32  
API: 05-081-05363



**Photo 3. Tubing stored on location perimeter.**



**Photo 4. Non reportable spill – stained soil.**



Inspection Photos  
Location Name: Carpenter 2-32  
API: 05-081-05363



**Photo 5. Debris from winter work.**



**Photo 6. Non reportable spill – stained soil.**