

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2019

Submitted Date:

05/01/2019

Document Number:

689802588**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 312776      Waldron, Emily      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 45898Name of Operator: KAISER-FRANCIS OIL COMPANYAddress: P O BOX 21468City: TULSA      State: OK      Zip: 74121**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
VanValkenburg, Charlotte		CharlotV@kfoc.net	<a href="#">Official Contact</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222373	WELL	SI	04/01/2017	GW	081-05363	CARPENTER 2-32	SI

**General Comment:**[Routine FIU inspection.](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No wellhead sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	05/30/2019

**Emergency Contact Number:**

Comment:	405-262-5511	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris from winter work on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/10/2019
Type	OTHER		
Comment:	Non reportable spills - stained soil in multiple places on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/30/2019
Type	STORAGE OF SUPL		
Comment:	Tubing stored on location perimeter.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/30/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	222373	Type:	WELL	API Number:	081-05363	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802606	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812536">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812536</a>