



**Location**

Overall Good:

Emergency Contact Number: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil around PU motor and base, and wellhead. see pic 3 & 4		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e Delinquent. 2/8/19	Date:	02/08/2019

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	fabricated fence around pump jack.		
Corrective Action:		Date:	

**Equipment:**

Type		#			corrective date
Type: Pump Jack		# 1			
Comment:	Unused pump jack, horses head, and other equipment on location. See pic 1&2				
Corrective Action:	Comply with Rule 603.f .			Date:	07/25/2019
Type: Prime Mover		# 1			
Comment:	Gas powered motor.				
Corrective Action:				Date:	
Type: Ancillary equipment		# 1			
Comment:	Automation Equipment.				
Corrective Action:				Date:	
Type: Other		# 1			
Comment:	Bradenhead appears to be plumbed to surface.				
Corrective Action:				Date:	
Type: Plunger Lift		# 1			
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203546 Type: WELL API Number: 001-09106 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well appears to be producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On 4/25/2019 at approximately 1030 I, Inspector Justin Medina conducted an on-site inspection at Ambush 24-22 Petroshare Corp. at 001-09106 in Adams County Colorado. While there, I observed producing well. This is a follow up inspection from Document # 688401011 At time of inspection the following possible compliance issues were found:                      Unused pump jack, horses head, and other equipment on location. See pic 1&amp;2                      Comply with Rule 603.f . 7/25/19                      Stained soil around PU motor and base. See pic 3&amp;4                      Properly treat or dispose of oily waste in accordance with 907.e Delinquent. 2/8/19                      Other CA from previous inspection appear to have been addressed.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.                      Continuing Education Inspection.</p>	medinaj	04/25/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402022173	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806893</a>
685100829	loc pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806887">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806887</a>