

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2019

Submitted Date:

05/01/2019

Document Number:

688402057**FIELD INSPECTION FORM**Loc ID 413614 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                | Comment                         |
|--------------|-------|--------------------------------------|---------------------------------|
| ,            |       | Cogcc.inspections@crestone<br>pr.com | <a href="#">ALL INSPECTIONS</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 412364      | WELL | PR     | 12/14/2010  | GW         | 014-20664 | SEARS 22-26   | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | Adequate |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                    |                                  |       |                 |
|--------------------|----------------------------------|-------|-----------------|
| Type: Plunger Lift | # 2                              |       | corrective date |
| Comment:           |                                  |       |                 |
| Corrective Action: |                                  | Date: |                 |
| Type: Bradenhead   | # 2                              |       |                 |
| Comment:           | Appears to be pumbed to surface. |       |                 |
| Corrective Action: |                                  | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 412364         | Type: WELL | API Number: 014-20664 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    | PR         |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment                             | User    | Date       |
|-------------------------------------|---------|------------|
| <a href="#">Routine inspection.</a> | silverr | 05/01/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 688402058    | loc pic     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812663">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812663</a> |