

Inspection Photos
Operator: Enduring Resources
Location/API #: 067-08735
Date: 4-22-2019



Photo 1. View of the northern project area from the northwestern edge facing eastward.



Photo 2. View of musk thistles (*Carduus nutans*) within the southern project area.



Photo 3. View of area within the northwestern reclamation area where road access was recently closed off, and revegetation appears to be progressing. Revegetation should be monitored in area where tracking remains.