

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

697600066**FIELD INSPECTION FORM**Loc ID 332752 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250103	WELL	PR	03/26/2019	GW	123-17906	UPRC 9-11I6	EI
250104	WELL	SI	11/01/2018	GW	123-17907	UPRC 9-12I6	EI
250105	WELL	SI	01/01/2019	GW	123-17908	UPRC 9-14I6	EI
446292	TANK BATTERY	CL	08/10/2017		-	FIVE RIVERS K 09-28D TANK	EI

General Comment:

[inspection of wells and closed battery facility 446292 nearest to wells REM 10370 equipment from battery 446292 has been removed from location](#)

[other batteries in area inspected separately under COGCC facility numbers](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	emergency contact information on each wellhead sign		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused equipment at UPRC 9-1416 well in attached photo		
Corrective Action:	Comply with Rule 603.f .	Date:	06/01/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: no spills observed at surface

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 2		
Comment:	123-17908 has no means of production		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 250103 Type: WELL API Number: 123-17906 Status: PR Insp. Status: EIFacility ID: 250104 Type: WELL API Number: 123-17907 Status: SI Insp. Status: EIFacility ID: 250105 Type: WELL API Number: 123-17908 Status: SI Insp. Status: EI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: no means of production present at well head

Corrective Action: _____ Date: _____

Facility ID: 446292 Type: TANK API Number: - Status: CL Insp. Status: EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697600067	unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4813930