

Inspection Photos
Location Name: Walker Ann #2
Location ID: 320177



Pic 1 oily waste near motor



Pic 2 oily waste near exhause

Inspection Photos
Location Name: Walker Ann #2
Location ID: 320177



Pic 3 stained soil near motor



Pic 4 stained soil at wellhead

Inspection Photos
Location Name: Walker Ann #2
Location ID: 320177



Pic 5 stained soil at wellhead possible leak



Pic 6

Inspection Photos
Location Name: Walker Ann #2
Location ID: 320177



Pic 7



Pic 8