

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

685100891**FIELD INSPECTION FORM**Loc ID 320177 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
,		dnr_cogccenforcement@state.co.us	
Condill, J.B.		jbcrog@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202912	WELL	PR	07/01/2018	OW	001-08317	WALKER ANN 2	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type SEPARATOR

Comment: 4' barb wire

Corrective Action:

Date:

Type TANK BATTERY

Comment: 4' barb wire

Corrective Action:

Date:

Type WELLHEAD

Comment: 4' barb wire around pump jack and wellhead.

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

1

Comment: appears to be plumbed to surface.

Corrective Action:

Date:

Type: Pump Jack

1

Comment: Stained soil around wellhead possible leak. see pic 4 &5

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 11/19/2018

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: Gas motor has stained soil under motor. see pic 1,2,3.

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

Date: 11/19/2018

Type: Bird Protectors

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.509843,-104.212699

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		39.509843,-104.212699

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	shares containment with oil tank.
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 202912	Type: WELL	API Number: 001-08317	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 5/2/19 at approximately 1100, Inspector Justin Medina conducted an on-site inspection at 001-08317 Walker Ann 2 Renegade oil and gas company llc. at Weld County Colorado. While there, I observed producing well.</p> <p>This is a follow up inspection for document # 688400455</p> <p>CA from previous inspection appear to have been addressed, however more leaks appear to be happening.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Gas motor has stained soil under motor. see pic 1,2,3. Delinquent 11/19/18</p> <p>Stained soil around wellhead possible leak. see pic 4 &5</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Delinquent 11/19/18</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	05/02/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100892	Loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814140