

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2019

Submitted Date:

04/26/2019

Document Number:

687904672**FIELD INSPECTION FORM**
 Loc ID 334003 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------------|
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bpx.com | SW Inspection Reports |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 301294 | WELL | PR | 02/01/2014 | GW | 067-09694 | SOUTHERN UTE DD 2 | PR |
| 301296 | WELL | PR | 07/01/2017 | GW | 067-09696 | SOUTHERN UTE DD 4 | PR |

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank labels and placards posted on tank. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Sign posted at entrance to location. Conditions have deteriorated sign and it needs to be replaced. | | |
| Corrective Action: | Comply with Rule 210.e. | Date: | 06/26/2019 |

| | |
|---------------------------|-------------------------------------|
| Emergency Contact Number: | |
| Comment: | Contact information posted on sign. |
| Corrective Action: | |
| | Date: _____ |

| | | | |
|---------------------------|--|-------|------------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | 2 valve sets that were pulled off separator inlet sitting along cattle panels. Return to service or remove unused equipment from location. | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 05/26/2019 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Cattle panels around produced water tank. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Cattle panels around wellhead and pump jack. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Flow Line | # 11 | | |
| Comment: | 4-4" flowlines from wellhead to separator. 2-2" flowlines from separator to produced water tank. 2-2" flowlines from separator to offsite produced water gathering system. 2-3" flowlines from separator outlet to join 1-4" common header and going offsite to dogleg. | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |

| | | | | | |
|---------------------------|-----|---|--|-------|--|
| Comment: | | MCC for VFD drive electric motors on pumpjacks. | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Bradenhead | # 2 | | | | |
| Comment: | | Badenhead plumbed to surface. | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Ancillary equipment | # 2 | | | | |
| Comment: | | Wellhead with PVC bradenhead access. | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Vertical Separator | # 2 | | | | |
| Comment: | | | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Gas Meter Run | # 2 | | | | |
| Comment: | | | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Bird Protectors | # 1 | | | | |
| Comment: | | Vent on produced water tank. | | Date: | |
| Corrective Action: | | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|--|---------------------|-------------|
| | | | | |
| Comment: | | No secondary containment. Double-wall tank with level control equipment installed. | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|----------|--|
| Type | |
| Comment: | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

| Inspected Facilities | | | | | | | | | |
|----------------------|------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 301294 | Type: | WELL | API Number: | 067-09694 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301296 | Type: | WELL | API Number: | 067-09696 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | | | | | |
| Compaction | Pass | Gravel | Pass | | | |
| Gravel | Pass | | | | | |
| Ditches | Pass | Compaction | Pass | | | |

Comment: [Banks around location that were disturbed during construction, now have vegetation and growth.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402023815 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808526 |
| 687904673 | Unused Equipment. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808513 |
| 687904674 | Location. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808514 |
| 687904675 | Location Sign. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808515 |