

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2019

Submitted Date:

04/26/2019

Document Number:

687904682**FIELD INSPECTION FORM**Loc ID 334315 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258539	WELL	PR	02/04/2003	GW	067-08361	FINNEY 4-12U	PR
286590	WELL	PR	10/14/2009	GW	067-09235	FINNEY 5-12U	PR

**General Comment:**[Site inspection with photos at the end of this report.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact information posted on sign.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	According to attached photo documents, Compressor had been removed prior to 6/14/2017. Flowlines for suction and discharge of compressor, and flowlines for produced water have been LOTO and are no longer in use so they are unused equipment that need to be removed.		
Corrective Action:	Comply with Rule 603.f.	Date:	07/26/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 8		
Comment:	1-3" flowline from wellhead to separator. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg. 1-2" flowline from separator dump valve to offsite produced water gathering system. 2-4" flowlines from wellhead to separator. 1-3" flowline from separator dump valve to offsite produced water gathering system. 1-4" flowline from separator to offsite dogleg.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead with PVC bradenhead access.		
Corrective Action:		Date:	

Type: Other	# 1		
Comment:	MCC for electric motor on pumpjack.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Compressor building with suction and discharge flowline piping as well as Produced water flowline piping that is no longer in service.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	Pigging station in corner of location.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258539	Type:	WELL	API Number:	067-08361	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			
Facility ID:	286590	Type:	WELL	API Number:	067-09235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402023817	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808529">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808529</a>
687904684	Unused flowlines suction/water	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808521">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808521</a>
687904685	Unused flowlines discharge/water	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808522">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808522</a>
687904686	Out of service date.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808523">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808523</a>
687904687	Unused flowlines at separator.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808524</a>
687904688	Location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808525">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808525</a>