

**Inspection Photos**  
**Location Name: FIEROZZO 42-1**  
**API #: 05-071-09646**  
**Insp. Doc. # 695100577**



Colorado Oil & Gas Conservation Commission  
36.99891, -104.48271, 156°  
2019/05/02 09:32:03



Colorado Oil & Gas Conservation Commission  
37.11547, -104.72551, 2016.0m, 128°  
2019/05/02 09:32:24

**PHOTO 1: LOCATION**

**PHOTO 2: METER HOUSE/WELL SIGN**

**Inspection Photos**  
**Location Name: FIEROZZO 42-1**  
**API #: 05-071-09646**  
**Insp. Doc. # 695100577**



**PHOTO 3: APPROXIMATELY 2" TO 3" S OF STANDING OILY WATER IN PRIME MOVER ENGINE SKID.**

**PHOTO 4: APPROXIMATELY 2' BY 3' AREA OF IMPACTED SOIL NEAR NORTHEAST SIDE OF PRIME MOVER ENGINE SKID.**

**Inspection Photos**  
**Location Name: FIEROZZO 42-1**  
**API #: 05-071-09646**  
**Insp. Doc. # 695100577**



**PHOTO 5: AREA OF SOIL IMPACTION EXTENDS AROUND  
CONCRETE AND UNDER PRIME MOVER ENGINE SKID.**

