

**Inspection Photos**  
**Location Name: ERNIE 31-6**  
**API #: 05-071-08716**  
**Insp. Doc. # 695100579**



Colorado Oil & Gas Conservation Commission  
37.11897, -104.71122, 1985.0m, 104°  
2019/05/02 11:17:16

**PHOTO 1: LOCATION**



Colorado Oil & Gas Conservation Commission  
37.11907, -104.71101, 1987.0m, 117°  
2019/05/02 11:04:12

**PHOTO 2: METER HOUSE/WELL SIGN**

**Inspection Photos**  
**Location Name: ERNIE 31-6**  
**API #: 05-071-08716**  
**Insp. Doc. # 695100579**




**PHOTO 3: APPROXIMATELY 1.5" OF STANDING OIL IN PRIME MOVER ENGINE SKID.**



**PHOTO 4: 1" PIPE IS DRIPPING PRODUCED WATER AND PUDDLING NEXT TO WELLHEAD. 1" VALVE IS CLOSED AND PIPE HAS A PLACTIC PLUG.**



**Inspection Photos**  
**Location Name: ERNIE 31-6**  
**API #: 05-071-08716**  
**Insp. Doc. # 695100579**



**PHOTO 5: WELL IS ON VACUUM**



**PHOTO 6: STORMWATER DRAINAGE DITCH NORTH OF LOCATION  
SHOWING SIGNS OF EROSION AND SEDIMENT MIGRATION.**



**Inspection Photos**  
**Location Name: ERNIE 31-6**  
**API #: 05-071-08716**  
**Insp. Doc. # 695100579**



**PHOTO 7: ANOTHER ANGLE OF STORMWATER DRAINAGE NORTH OF LOCATION SHOWING SIGNS OF EROSION AND SEDIMENT MIGRATION.**



**PHOTO 8: CLOSER LOOK AT EROSION FROM PREVIOUS PHOTOS (PHOTO #6 & #7)**



**Inspection Photos**  
**Location Name: ERNIE 31-6**  
**API #: 05-071-08716**  
**Insp. Doc. # 695100579**



**PHOTO 9: ANOTHER IMAGE SHOWING PROXIMITY OF  
STORMWATER DRAINAGE TO LOCATION PHOTO TAKEN FROM  
THE NORTH LOOKING SOUTH**



**PHOTO 10: ANOTHER IMAGE SHOWING PROXIMITY OF  
STORMWATER DRAINAGE TO LOCATION PHOTO TAKEN FROM  
THE NORTHEAST LOOKING SOUTHWEST**



**Inspection Photos**  
**Location Name: ERNIE 31-6**  
**API #: 05-071-08716**  
**Insp. Doc. # 695100579**



**PHOTO 11: ANOTHER IMAGE SHOWING STORMWATER DRAINAGE THE ENTIRE LENGTH OF LOCATION TAKEN FROM THE NORTHEAST LOOKING SOUTHWEST**



**PHOTO 10: IMAGE SHOWING STORMWATER DRAINAGE. PHOTO TAKEN FROM THE WEST LOOKING EAST**