

**Inspection Photos**  
**Location Name: ERNEST 21-7**  
**API #: 05-071-06764**  
**Insp. Doc. # 695100581**



**PHOTO 1: LOCATION**



**PHOTO 2: METER HOUSE/WELL SIGN**



**Inspection Photos**  
**Location Name: ERNEST 21-7**  
**API #: 05-071-06764**  
**Insp. Doc. # 695100581**



**PHOTO 3: CULVERT ON MAIN ROAD SOUTHEAST OF LOCATION IS PLUGGED AND NEEDS CLEANED.**



**PHOTO 4: IMAGE FROM STANDING ON CULVERT ON DOWN GRADIENT SIDE OF ROW.**



**Inspection Photos**  
**Location Name: ERNEST 21-7**  
**API #: 05-071-06764**  
**Insp. Doc. # 695100581**



**PHOTO 5: EROSION NEAR CULVERT OUTLET ON DOWN GRADIENT SIDE OF CULVERT.**



**PHOTO 6: ANOTHER ANGLE OF EROSION ON DOWN GRADIENT SIDE OF CULVERT**