

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/03/2019

Document Number:

695100579**FIELD INSPECTION FORM**
 Loc ID 308843 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283270	WELL	PR	06/01/2018	GW	071-08716	ERNIE 31-6	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	WELL SIGN POSTED ON METER HOUSE STATES OPERATOR IS PIONEER FORM 10 DOC# WAS APPROVED ON		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	06/02/2019

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	PHOTO 4: 1" PIPE IS DRIPPING PRODUCED WATER AND PUDDLING NEXT TO WELLHEAD. 1" VALVE IS CLOSED AND PIPE HAS A PLACTIC PLUG.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 06/03/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:		corrective date
Type: Bradenhead	# 1	
Comment:	IS PLUMBED TO SURFACE	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	TELEMETRY EQUIPMENT	
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:	Vacuum pump observed on well without COGCC approval. PHOTO 5: WELL IS ON VACUUM	
Corrective Action:	Provide COGCC with documentaton showing approval of use of vacuum pump. PROVIDE INSPECTOR tom.beardslee@state.co.us a list of all wells with compressors and a list with all wells being produced on a vacuum.	Date: 05/17/2019

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	283270	Type:	WELL	API Number:	071-08716	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: PHOTO 6 through 10: STORMWATER DRAINAGE DITCH NORTH OF LOCATION SHOWING SIGNS OF EROSION AND SEDIMENT MIGRATION.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/02/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	285705	200093488	
	285705	200093488	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100580	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814496