

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/02/2019

Submitted Date:

05/03/2019

Document Number:

695100581

FIELD INSPECTION FORM
 Loc ID 307661 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89185	WELL	PR	02/13/2005	GW	071-06764	ERNEST 21-7	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	WELL SIGN POSTED ON METER HOUSE STATES OPERATOR IS PIONEER FORM 10 DOC# WAS APPROVED ON		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	06/02/2019

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 0		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS NOT PLUMBED TO SURFACE		
Corrective Action:	COMPLY WITH NTO	Date:	06/02/2019
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 89185	Type: WELL	API Number: 071-06764	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: PHOTO 3: CULVERT ON MAIN ROAD SOUTHEAST OF LOCATION IS PLUGGED AND NEEDS CLEANED.
 PHOTO 4: IMAGE FROM STANDING ON CULVERT ON DOWN GRADIENT SIDE OF ROW.
 PHOTO 5: EROSION NEAR CULVERT OUTLET ON DOWN GRADIENT SIDE OF CULVERT.
 PHOTO 6: ANOTHER ANGLE OF EROSION ON DOWN GRADIENT SIDE OF CULVERT

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 06/02/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100582	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814497