

Construction and Stormwater Inspection

May 2, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 455456

Inspection Document #: 697500072

Weld County, CO

NWNE Section 18 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EAST AULT 18-C PAD
Location ID: 455456



Photo 1. Photo taken from the western location, facing South. Photo illustrates a silt fence BMP, and the cut slope has been tracked.



Photo 2. Photo taken from the southwestern location, facing East. Photo illustrates the south-facing topsoil has been temporarily stabilized and silt fence BMP installed.

The western and northern perimeter of the location would appear to control for run-on, not run-off; therefore, the silt fence stakes are not properly installed.

Inspection Photos
Location Name: EAST AULT 18-C PAD
Location ID: 455456



Photo 3. Photo taken from the northwestern well pad, facing North. Operator has properly stabilized the well pad area to control for dust and erosion per Rule 1002.e.

Inspection Photos
Location Name: EAST AULT 18-C PAD
Location ID: 455456



Photo 4. Photo taken from the northwestern well pad, facing East. See comments under Photo 3.

Inspection Photos
Location Name: EAST AULT 18-C PAD
Location ID: 455456



Photo 5. Photo taken from the northwestern well pad, facing East. See comments under Photo 1.