

Inspection Photos
Location Name: IDA 42-20
API #: 05-071-07330
INSP. #:695100585



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: IDA 42-20
API #: 05-071-07330
INSP. #:695100585



**PHOTO 3: RUST COLORED IMPACTED SOIL APPROXIMATELY 4' BY 3'
AREA AROUND WELLHEAD**

Comply with Rule 603.f . REMOVE IMPACTED SOIL



**PHOTO 4: STORMWATER EROSION AT CULVERT NORTH OF LOCATION
ON MAIN ROW.**

Install or repair required BMPs per Rule 1002.f.

Inspection Photos
Location Name: IDA 42-20
API #: 05-071-07330
INSP. #:695100585



PHOTO 5: STORMWATER EROSION AT CULVERT NORTH OF LOCATION ON MAIN ROW.

Install or repair required BMPs per Rule 1002.f.



PHOTO 4: STORMWATER EROSION AT CULVERT NORTH OF LOCATION ON MAIN ROW.

Install or repair required BMPs per Rule 1002.f.