

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/29/2019

Submitted Date:

04/29/2019

Document Number:

679703886**FIELD INSPECTION FORM**Loc ID 315358 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	<a href="#">All inspections</a>
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230694	WELL	PR	12/01/2007	GW	103-08362	PHILADELPHIA CREEK 21	PR

**General Comment:**[COGCC Inspection Report Summary.](#)[On 4/29/2019 at approximately 10:30, inspector Rick Moran, conducted a follow up inspection at Robert L. Bayless Producer's well Philadelphia Creek 21 in Rio Blanco county.](#)[While there I conducted a follow up inspection of FIR documents 679703455 from 3/25/2019, and 679702259 from 12/19/2018.](#)[During this inspection the following possible compliance issues were observed as uncompleted :](#)

- [1\). Deadman marker lying on ground.](#)

[A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[This is a summary of inspection report 679703886.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 505-327-0880

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	One deadman marker is lying on ground.		
Corrective Action:	Comply with Rule 1003.a	Date:	04/15/2019
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	230694	Type:	WELL	API Number:	103-08362	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing well								
Corrective Action:				Date:					

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration, erosion, or soil movement on location.

Corrective Action:

Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Blowdown      Lined: NO      Pit ID:      Lat: 39.876340      Long: -108.711920

Reference Point:       Other:       Length:       Width:

**Lining:**

Liner Type:      Liner Condition:

Comment: Pit located next to wellhead. No pipe going into pit.

Corrective Action

Date:

**Fencing:**

Fencing Type: Netting/Fence com      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Fence/Net Combo      Netting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Type: Blowdown      Lined: NO      Pit ID:      Lat: 39.876500      Long: -108.711510

Reference Point:       Other:       Length:       Width:

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Netting/Fence com      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Fence/Net Combo      Netting Condition: Good

Inspector Name: Moran, Rick

Comment:		Date:
Corrective Action		
Anchor Trench Present:                      Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>YES</u>		
Comment:		Date:
Corrective Action		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402025719	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4810004">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4810004</a>
679703887	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4809997">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4809997</a>