

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402033369

Date Received:  
05/06/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Tesla Dougherty

970-304-5245

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679600584

Inspection Date: 04/04/2019

FIR Submit Date: 04/04/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 333063

Location Name: NOFFSINGER F-65N65W Number: 2NWNW County: WELD

Qtrqr: NWN Sec: 2 Twp: 5N Range: 65W Meridian: 6  
W

Latitude: 40.433250 Longitude: -104.637497

FACILITY - API Number: 05-123- -00 Facility ID: 292972

Facility Name: NOFFSINGER F Number: 2-5

Qtrqr: NWN Sec: 2 Twp: 5N Range: 65W Meridian: 6  
W

Latitude: 40.433250 Longitude: -104.637497

CORRECTIVE ACTIONS:

1 CA# 123864

Corrective Action: Comply with Rule 603.f .

Date: 05/04/2019

Response: CA COMPLETED

Date of Completion: 04/29/2019

Operator  
Comment:

Unused tubing has been cleaned up

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 123865

Corrective Action: Comply with Rule 603.f .

Date: 05/04/2019

Response: CA COMPLETED

Date of Completion: 04/29/2019

Operator  
Comment: Unused piping has been removed from location

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 123866

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/04/2019

Response: CA COMPLETED

Date of Completion: 04/29/2019

Operator  
Comment: The stained soil at the master valve has been cleaned up

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**4** CA# 123867

Corrective Action: Comply with Rule 603.f .

Date: 05/04/2019

Response: CA COMPLETED

Date of Completion: 04/29/2019

Operator  
Comment: The unused equipment in the meter house has been removed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 5/6/2019 1:20:14 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files