

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2019

Submitted Date:

05/01/2019

Document Number:

679703927**FIELD INSPECTION FORM**
 Loc ID 316014 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone        | Email                       | Comment                         |
|-----------------|--------------|-----------------------------|---------------------------------|
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us  |                                 |
| , Utah Gas Corp | 720-425-0303 | inspections@utahgascorp.com | <a href="#">All inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 231924      | WELL | PR     | 08/01/2018  | GW         | 103-09595 | LOWER HORSE DRAW A 2223 | PR          |

**General Comment:**[COGCC Inspection Report Summary.](#)

On 5/1/2019 at approximately 15:30, inspector Rick Moran, conducted a routine inspection at Utah Gas's well Lower Horse Draw Field 2223 in Rio Blanco county.

During this inspection the following possible compliance issues were observed:

- 1) Container label illegible. Photo 2. Due by 7-1-2019.
- 2) Unmarked deadman. Photo 3. Due by 5-20-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679703927.

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | TANK LABELS/PLACARDS                    |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | WELLHEAD                                |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | BATTERY                                 |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | CONTAINERS                              |       |            |
| Comment:             | Methanol container sign illegible.      |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.e. | Date: | 07/01/2019 |

Emergency Contact Number:

Comment: 970-693-6021

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|  |      |        |  |
|--|------|--------|--|
| <b>Spills:</b>   |      |        |  |
| Type   | Area | Volume |  |
| In Containment:  | No   |        |  |
| Comment:   |      |        |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |   |       |                 |
|-----------------------------------|---|-------|-----------------|
| <b>Equipment:</b>                 |   |       | corrective date |
| Type: Horizontal Heated Separator | # 1   |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Ancillary equipment         | # 1   |       |                 |
| Comment:                          | One container of methanol with secondary containment. |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Gas Meter Run               | # 1   |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |

|                          |   |  |                  |
|--------------------------|---|--|------------------|
| Type: Plunger Lift       | # 1   |  |                  |
| Comment:                 |   |  |                  |
| Corrective Action:       |   |  | Date:            |
| Type: Deadman # & Marked | # 4   |  |                  |
| Comment:                 | One guy line anchors not marked. Marker is lying on ground. |  |                  |
| Corrective Action:       | Install proper guy line markers per Rule 1003.a             |  | Date: 05/20/2019 |

**Tanks and Berms:**

|                    |   |          |          |         |                       |       |
|--------------------|---|----------|----------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type     | Tank ID | SE GPS                |       |
| PRODUCED WATER     | 1 | <50 BBLs | Open Top |         | 39.853660,-108.959320 |       |
| Comment:           |   |          |          |         |                       |       |
| Corrective Action: |   |          |          |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 50 bbl   |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    |       |
|                    |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: |       |
|                    | Date: |

| Inspected Facilities |                                 |       |      |             |           |         |    |               |    |
|----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 231924                          | Type: | WELL | API Number: | 103-09595 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                                 |       |      |             |           |         |    |               |    |
| Comment:             | Producing well on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:   |                                 |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [No apparent soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402029437    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812601">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812601</a> |
| 679703928    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812588">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812588</a> |