

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2019

Submitted Date:

05/01/2019

Document Number:

687904703**FIELD INSPECTION FORM**
 Loc ID 333433 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215270	WELL	PR	11/25/1986	GW	067-06875	BUFORD WAYT A 1	PR
293705	WELL	PR	11/27/2007	GW	067-09443	BUFORD WAYT A 3	PR

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels posted on produced water tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign at entrance is not legible and needs to be replaced.		
Corrective Action:	Comply with Rule 210.e.	Date:	06/01/2019

Emergency Contact Number:

Comment: Contact information is not legible on sign.

Corrective Action: Comply with Rule 210.e.

Date: 06/01/2019

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Piping spool sitting on pumpjack frame on Buford A1 is unused equipment.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/01/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjacks.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separator, meter house and produced water tank.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Location fenced in barbed wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Wellheads on location.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:	On separator stack and produced water tank vent.	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	PVC bradenhead access.	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	MCC for VFD driven electric motors.	
Corrective Action:		Date:
Type: Flow Line	# 13	
Comment:	2-3" flowlines from wellheads to separator. 2-2" flowlines from wellhead blowdown to produced water tank. 2-2" flowlines from separator to produced water tank. 2-2" flowlines from separator dump valve to offsite produced water gathering system. 2-3" flowlines from separator to meter house. 2-3" flowlines from meter house merging into 1-4" flowline to offsite dogleg.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:	Produced water tank with level control indication.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 215270 Type: WELL API Number: 067-06875 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 293705 Type: WELL API Number: 067-09443 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402029272	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812435
687904704	Location sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812428
687904705	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812429
687904706	Unused equipment spool piece.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812430