

**Inspection Photos**  
**Location Name: Leroy McCaw B #1**  
**API: 05-067-07009**



**Leroy McCaw B #1 location photo.**



**Spill/Release Point ID #463807 source.**

**Inspection Photos**  
**Location Name: Leroy McCaw B #1**  
**API: 05-067-07009**



**Valve set has been fenced off with safety fencing and excavation has been partially backfilled.**



**View to the north from the valve set.**



**Inspection Photos**  
**Location Name: Leroy McCaw B #1**  
**API: 05-067-07009**



**Drainage feature leading into freshwater emergent wetland was dry at the time of this inspection.**



**View to the south from the edge of the Leroy McCaw B #1 location.**