

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

697600066

FIELD INSPECTION FORMLoc ID 332752 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250103	WELL	PR	03/26/2019	GW	123-17906	UPRC 9-11I6	EI
250104	WELL	SI	11/01/2018	GW	123-17907	UPRC 9-12I6	EI
250105	WELL	SI	01/01/2019	GW	123-17908	UPRC 9-14I6	EI
446292	TANK BATTERY	CL	08/10/2017		-	FIVE RIVERS K 09-28D TANK	EI

General Comment:

inspection of wells and closed battery facility 446292 nearest to wells REM 10370 equipment from battery 446292 has been removed from location

other batteries in area inspected separately under COGCC facility numbers

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	emergency contact information on each wellhead sign		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused equipment at UPRC 9-1416 well in attached photo		
Corrective Action:	Comply with Rule 603.f .	Date:	06/01/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: no spills observed at surface

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 2		
Comment:	123-17908 has no means of production		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 250103 Type: WELL API Number: 123-17906 Status: PR Insp. Status: EIFacility ID: 250104 Type: WELL API Number: 123-17907 Status: SI Insp. Status: EIFacility ID: 250105 Type: WELL API Number: 123-17908 Status: SI Insp. Status: EI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: no means of production present at well head

Corrective Action: _____ Date: _____

Facility ID: 446292 Type: TANK API Number: - Status: CL Insp. Status: EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402030804	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4813947
697600067	unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4813930