

Inspection Photos

Location Name: FIREHAWK 34-26

API #: 05-071-08389

INSP. #:695100622



PHOTO 1: LOCATION

**PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS
INACCURATE Install sign to comply with Rule 210.b. CA DUE DATE
7/8/19**

Inspection Photos

Location Name: FIREHAWK 34-26

API #: 05-071-08389

INSP. #:695100619



Colorado Oil & Gas Conservation Commission
37.22533, -104.74558, 2183.0m, 137°
2019/05/08 10:19:48



Colorado Oil & Gas Conservation Commission
37.22524, -104.7457, 2099.0m, 31°
2019/05/08 10:17:37

PHOTO 3: OIL SHEEN ON WATER IN COMPRESSOR SKID CONTAINMENT THERE IS ALSO IMPACTED SOIL ALONG THE WEST EDGE OF COMPRESSOR SKID. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 6/8/19

PHOTO 4: THERE IS AN AREA APPROXIMATELY 7' CIRCLE OF IMPACTED SOIL LEADING FROM THE SOUTHWEST CORNER OF COMPRESSOR SKID. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. CA DATE 6/8/19

Inspection Photos
Location Name: FIREHAWK 34-26
API #: 05-071-08389
INSP. #:695100619



Colorado Oil & Gas Conservation Commission
37.22516, -104.74551, 2106.0m, 34°
2019/05/08 10:17:55



Colorado Oil & Gas Conservation Commission
37.22534, -104.74558, 2183.0m, 13°
2019/05/08 10:21:00

PHOTO 5: UNUSED EQUIPMENT ON LOCATION EAST OF COMPRESSOR SKID. COMPLY WITH RUL 603.f. CA DATE 6/8/19

PHOTO 5: WELL APPEARS TO BE ON A VACUUM. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 5/23/19