

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2019

Submitted Date:

05/10/2019

Document Number:

695100622**FIELD INSPECTION FORM**

Loc ID 308642 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277849	WELL	PR	04/09/2014	GW	071-08389	FIREHAWK 34-26	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS INACCURATE		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	07/08/2019

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4: THERE IS AN AREA APPROXIMATELY 7' CIRCLE OF IMPACTED SOIL LEADING FROM THE SOUTHWEST CORNER OF COMPRESSOR SKID.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	06/08/2019
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5: UNUSED EQUIPMENT ON LOCATION EAST OF COMPRESSOR SKID.		
Corrective Action:	COMPLY WITH RUL 603.f.	Date:	06/08/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Compressor	#		
Comment:	PHOTO 5: WELL APPEARS TO BE ON A VACUUM.		
Corrective Action:	Provide COGCC with documentation showing approval of use of vacuum pump.	Date:	05/23/2019
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	NOT PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	PHOTO 3: OIL SHEEN ON WATER IN COMPRESSOR SKID CONTAINMENT THERE IS ALSO IMPACTED SOIL ALONG THE WEST EDGE OF COMPRESSOR SKID.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 06/08/2019
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277849	Type:	WELL	API Number:	071-08389	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100624	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820859